

Release Notes

Xerox AltaLink 80XX Series

Release Version 100.xxx.107.28600

RELEASE DATE OCTOBER 16, 2017

Product	Software Version
Xerox® AltaLink® C8030/C8035	100.001.107.28600
Xerox® AltaLink® C8045/C8055	100.002.107.28600
Xerox® AltaLink® C8070	100.003.107.28600
Xerox® AltaLink® B8045/55/65/75/90	100.008.107.28600

Purpose

This release contains fixes such as the following.

AltaLink C80xx

- Image Quality improvements when using Postscript print driver, with print quality setting in the default or “standard” mode
- Image Quality improvements when using PCL print driver with print quality setting in the default or “standard” mode
- Image Quality improvements when Copying
- Scan Image Quality improvements. Improved color reproduction and capture of highlights when scanning to Email, USB, Workflow Scanning, etc
- Provides fixes to address 319-409 faults.

If image quality issues are still present, ensure you have performed a Copy Calibration and a Print Calibration. If these procedures do not address the issue, contact customer support.

AltaLink B80xx

- B8090 slow feed when pulling from tray 1 only
- High Volume Finisher (HVF) eject timing problem is causing mis-stacking and jams

AltaLink C80xx and B80xx

- Card Reader Notification pop-up message. Eliminated card reader pop-up message, "Card Reader Detected", after waking up from power saver/sleep mode
- Secure Print/Held Jobs. Resolved intermittent issue where secure print or held jobs are not visible at the local UI (however are visible on device web page)
- DFS scanning fails following the DFS referral. DNS request does not contain the domain component.
- Scanning to Netapp Server Fails with a login failure.
- After exiting power saver mode, swiping your card over the USB reader results in the reader beeping but no change occurs on the MFD LUI.
- When device set to DHCP, it is only grabbing the IP, Subnet Mask and Gateway and does not appear to grab DHCP Server info or DNS Addresses.
- When they put the character "&" in the LDAP filter field on the web UI, the filter cannot be saved.
- Remote Control Panel displays a black screen